ATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01		(X3) DATE SURVEY COMPLETED		
		315464	B. WING		04/25/2019	
NAME OF PROVIDER OR SUPPLIER CARE ONE AT EVESHAM				STREET ADDRESS, CITY, STATE, ZIP CODE 870 EAST ROUTE 70 MARLTON, NJ 08053		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORR (EACH CORRECTIVE ACTION SI CROSS-REFERENCED TO THE AF DEFICIENCY)	HOULD BE COMPLETIO	
E 000	Initial Comments		E OC	o		
	Emergency Preparedness					
K 000	Appendix Z-Emergen Provider and Supplie	quirements for Long Term	К 00	0		
	LIFE SAFETY CODE	E 101: 2012.				
K 511 SS=D	•		K 51	1	5/15/19	
	Utilities - Gas and Ele Equipment using gas complies with NFPA s electrical wiring and e NFPA 70, National El	or related gas piping 54, National Fuel Gas Code, equipment complies with ectric Code. Existing inue in service provided no				
	by: Based on observatio 4/16/2019, in the pres Regional Director of I and Maintenance Director determined that the fa	sence of the facility's Hospitality Services (RDHS)		 Electrical outlets were secure tested. Maintenance Director and As inspected the entire building and addressed any other identified a 	sistant d	

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES

PRINTED: 06/08/2022 FORM APPROVED OMB NO. 0938-0391

		ND HUMAN SERVICES MEDICAID SERVICES			FORI	D: 06/08/202 MAPPROVE D. 0938-039	
TATEMENT OF DEFICIENCIES ND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 315464		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01			(X3) DATE SURVEY COMPLETED		
		B. WING		04/25/2019			
NAME OF PROVIDER OR SUPPLIER CARE ONE AT EVESHAM			STREET ADDRESS, CITY, STATE, ZIP CODE 870 EAST ROUTE 70 MARLTON, NJ 08053				
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORREC (EACH CORRECTIVE ACTION SHOL CROSS-REFERENCED TO THE APPR DEFICIENCY)	JLD BE	(X5) COMPLETION DATE	
K 511	 following: During a tour of the b the RDHS and MD, t following: 1. At 10:16 a.m., the electrical outlets inside to the door bed were touched, the resident outlet and a light was outlet. 2. At 10:36 a.m., the conducted an intervie One resident a electrical outlets in th you ask them to fix th The surveyor observe an electrical outlet wit telephone charger ar the bed plugged in th moved when touched The surveyor also ob 	bde. e was evidenced by the building in the presence of the surveyor observed the surveyor observed two de resident room next loose and moved when is bed was plugged into one is plugged into the second surveyor observed and ew inside resident room isked the surveyor, "The is room are very loose, can nem." ed by the door near bed one, th a light and a cell ind one electrical outlet with nat were both loose and	K 5	 3. Maintenance personnel were in-serviced on April 17, 2019 on M inspection and reporting/repair of I outlets. 4. Maintenance Director will condu weekly inspections for 8 weeks an findings will be forwarded to the Q committee quarterly for 2 quarters review and any recommendations. 	ct 1X d API for		

3. At 10:50 a.m., the surveyor observed inside resident room one electrical outlet by the window bed that was loose and moved when touched. There was an opplugged into this electrical outlet.
4. At 11:06 a.m., the surveyor observed inside resident room one electrical outlet between the surveyor observed inside resident room one electrical outlet between the surveyor observed inside resident room one electrical outlet between the surveyor observed inside resident room one electrical outlet between the surveyor observed inside resident room one electrical outlet between the surveyor observed inside room one electrical outlet between the surveyor observed inside room one electrical outlet between the surveyor observed inside room one electrical outlet between the survey of t

resident room **constant** one electrical outlet between the two beds was loose and moved when touched.

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:0DZO21

Facility ID: NJ156002

If continuation sheet Page 2 of 3

		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING		
		315464	B. WING			
NAME OF PROVIDER OR SUPPLIER CARE ONE AT EVESHAM				STREET ADDRESS, CITY, STATE, ZIP CO 870 EAST ROUTE 70 MARLTON, NJ 08053	04/25/2019 CODE	
(X4) ID PREFIX TAG	(EACH DEFICIEN	TATEMENT OF DEFICIENCIES CY MUST BE PRECEDED BY FULL & LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF ((EACH CORRECTIVE ACTI CROSS-REFERENCED TO T DEFICIENC	ION SHOULD BE COMPLETE HE APPROPRIATE DATE	
K 511	Continued From pag	je 2	К 5	11		
	NJAC 8:39 -31.1(d) NFPA 70					

FORM CMS-2567(02-99) Previous Versions Obsolete

Facility ID: NJ156002

If continuation sheet Page 3 of 3